

Service Note: F1600WT-01



General Information

Service note number:	F1600WT-01
Short description:	No cracked hinge issue on OB2100 13" Display Cover
Supersedes:	-

Administrative Information

Service note objective:	Info only
Recommended action:	Not applicable
Originating entity:	0264
Expiration date:	-
Service type:	Not applicable
No of labor hours paid by div:	0.000
Cost of parts:	Not applicable
Cost of travel:	Not applicable
Service inventory:	Not applicable
Used Parts:	Not applicable

No parts are needed for this Service Note.

Detailed Service Note Content

Service Note Numbers:

OmniBook F1600W- F1600N- F1600WT- F1600NT-
2100-07 01 01 01 01

HP Model and Description

HP OmniBook 3100

To Be Performed By: HP Qualified Service Personnel

Situation

This is a placeholder Service Note only. There is now an OmniBook 2100 with a 13" display. The problem of possible cracks in the hinge area on the outside of 13" Display Covers was fixed, so the issue applies to some OmniBook 3100s but does NOT apply to OmniBook 2100s, even when they have a 13 inch display.

Service Note 3100-07 points out where the crack can occur on OmniBook 3100s and how to know if an OmniBook 3100 contains the fixed design or the older, vulnerable design.

Solution/Action

No action applies. This is a placeholder Service Note only.

15 September 1998

© 1998 HEWLETT-PACKARD COMPANY

PRINTED IN U.S.A.

[Back to the index](#)