

On the 4016DX (250-5001), 4020LX (250-5120), 4025LX (250-5125), 4033LX (250-5130), and 5000MC (250-6000), the printer ports are defined differently with SCO Xenix release 2.2.4 (250-5200) or 2.3.2 GT (250-5203). The chart below shows the correct port number for xenix and the port number under the CMOS setup for the on board printer port.

CMOS Printer Option	Xenix Printer Port
Printer-1	lp1
Printer-2	lp0
Printer-3	lp2

All other computers that do not control the on board printer port by the CMOS setup, will be as follows:

Printer Port Number	Xenix Printer Port
lpt-1	lp0
lpt-2	lp1
lpt-3	lp2